

SITE INSPECTION REVIEW FORM

SITE NAME: Diamond Aerosol, Woodglen and Anthony Roads
ALIASES: Glen Garner, Hunterdon County, New Jersey
SITE I.D.#: EPA ID No. NJ04964638

ITEM

COMPLETE ?
YES NO*

SITE LOCATION (INCLUDING MAP)

X

~~SITE~~ BACKGROUND

X

ENVIRONMENTAL SETTING (GEOLOGY, HYDROLOGY,
METEOROLOGY, ECOLOGY + LAND USE)WASTE DESCRIPTION (PRESENCE + CONDITION OF
WASTE + WASTE MANAGEMENT UNITS)

X

LABORATORY RESULTS (CORRELATED TO SAMPLE LOCATION MAP)

x Not completed

HRS PRE - SCORE (PRELIMINARY + PROJECTED)

X

POTENTIAL FOR DIRECT CONTACT

x

CONCLUSIONS + RECOMMENDATIONS

REFERENCES

X

HRS PRE-SCORE: PRELIMINARY SCORE = 9.15

PROJECTED SCORE = 19.9



COMMENTS:

1. It is advisable to give numerical order to ~~the~~ the pages inside of each attachment to prevent the loss of the documents
2. There are two pieces of scheme in Attachment "0" and one piece of it in Attachment 2 (?) They are supposed to ~~be~~ correlated to laboratory results. These "maps" are of very poor quality and almost unreadable
3. There is no ground water sampling location map correlated to laboratory results.

The site is still operating and should be under RCRA regulation. All these documents should be sent to RCRA for further decision.

REVIEWED BY:

G. Tsoukanova

DATE:

03/31/90

*IF ANY ITEM IS LACKING INFORMATION PLEASE DESCRIBE IN COMMENTS